



Customer :John Jameson

Vehicle: 00 323i

Mileage: 59219

Tech: Tim. C

Date: 2/13/17

Vehicle Evaluation Report

This courtesy inspection is a series of visual examinations performed by highly trained technicians to identify potential concerns before they become major repairs. Regular inspections will help you keep your vehicle performing at an optimal and safe level. In the event that additional services are recommended or noted during the inspection, your service advisor will speak with you about the available options and procedures. As this is primarily a visual inspection, this is not designed nor can it be, an exhaustive list. A lack of recommendations does not preclude an unexpected failure of component or system in the near or distant future.

	OK	Needs Attention	Needs Immed Attention	
1 Tires (see Below)	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	From 05 cracked and aged. Recommend replacing
2 Alignment	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
3 Front Brakes	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	3/4mm ABS Pressure sensor fault codes
4 Rear Brakes	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	6/7mm Brake fluid needs service
5 Front Suspension (Bushings/Joints/Links)	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Lower bushings have play
6 Rear Suspension (Bushings/Joints/Links)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Rear Trailing Arm Bushings have minor cracks
7 Front Shocks/Mounts	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Left Front Shock leaking hydraulic fluid
8 Rear Shocks/Mounts	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Right Rear Shock Leaking hydraulic Fluid
9 Power Steering (Hoses/Steering Rack/Joints/Boots)	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	hoses leaking, fluid needs service
10 Cooling System (Water Pump/T-stat/Fans)	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Thermostat is leaking coolant
11 Radiator (Expansion Tank/Hoses)	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	hoses are worn/swollen
12 Heater (Hoses/Temp°)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	121°F
13 Air Conditioning (Temp°)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
14 Engine (Gaskets/Hoses/Mounts)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
15 Drive Belts/Tensioner	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Tensioner bearings worn
16 Air Filters & Cabin/Micro Filters	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	replaced with service
17 Transmission (Seals/Leaks/Mounts)	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Shifter shaft leaking transmission fluid, mounts worn
18 Transfer Case (F.C./Mounts)	N/A	<input type="checkbox"/>	<input type="checkbox"/>	
19 Differential Front & Rear (Leaks/Mounts)	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Mounts cracking and separating
20 Axles (Boots/Drive Line/Flex Joint)	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Right Rear Differential seal seeping differential fluid
21 Exhaust System (Cond/Mounts)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
22 Battery & Cables (Faults/Cond./Charge output)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	State of charge 54%
23 Lights & Mirrors (Electrochrom/Lenses/Function)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
24 Wiper Operations (Washer Pump/Front & Rear)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
25 Glass / Windows/ Locks	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	locking system has unlock relay fault codes
26 Exterior (Trim Mouldings/Roudel/FenderLiner/Bumper)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
27 Hood & Trunk Shocks	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
28 Convertible Top Function (if Applicable)	N/A	<input type="checkbox"/>	<input type="checkbox"/>	
29 CBS Data & Warning lights	N/A	<input type="checkbox"/>	<input type="checkbox"/>	DSC warning light is on.

Fluids: Level & Condition

- ok Engine Oil (Check Level & Cond)
- Coolant PH / Glycol 8.0 / 60% needs service
- x Brake Fluid 4 %
- x P/S Emulsified
- ok Washer Fluid

TIRE PRESSURES

LF: 32 psi	RF: 32 psi
LR: 36 psi	RR: 36 psi

TIRE TREAD DEPTH

LF: 4 /32" 05 Production date	RF: 3 /32" 05 Production date
LR: 3 /32" 05 Production date	RR: 3 /32" 05 Production date